
Meridian 1

QCA144 1.5 MB/S Remote Peripheral Equipment Cabinet Appendix A

Maintenance and equipment replacement

Document Number: 553-2601-500A

Document Release: Standard 2.0

Date: December 1994

© 1987, 1994

All rights reserved

Printed in the United States of America

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Revision history

February 2, 1988

Version 1.0. This appendix is reissued to remove references to rectifiers other than the QRF12 –48 rectifier supplied with the cabinets. Changes to the practice are indicated by a vertical bar in the margin next to the affected item.

December 1994

Standard, release 2.0. Updated to new template and editorial changes added.

Contents

General	1
Fault detection and locating	3
Overlay programs	3
Alarm indications	3
Fault locating	3
Fault clearing procedures	3
Equipment replacement	11
Equipment replacement procedures	11

List of figures

Figure 1	
Battery cell connections	13
Figure 2	
Expansion battery unit connections	16
Figure 3	
Connections at rear of cabinet	18
Figure 4	
Cabinet top assembly	23
Figure 5	
Shelf assignments	29
Figure 6	
Cooling unit connections	31

List of tables

Table 1	
Alarm indications	4
Table 2	
Fault indicators and possible causes	6